
Fig.1



BEST AVAILABLE COPY

Fig.2




Fig.3




Fig.4




Fig.5





Fig.6



7/29




Fig.7

8/29




Fig.9




Fig. 10





Fig.11



12/29




Fig. 1.




Fig. 13

Fig.14






Fig.15




16/29


Fig.16



17/29

Fig.17





18/29

Fig. 18





Fig.19



20/29

Fig. 20




Fig.21




Fig.22




Fig. 23

		20120	
261 μ m/7.0 μ J	253 μ m/22 μ m/18 μ m		4 m
265 μ m/7.0 μ J	256 μ m/22 μ m/15 μ m		2 µ m
275 µ m/7.0 µ J	263 µ m/22 µ m/8 µ m		m π 0
LIGHT-CONVERGING POSITION/ENERGY	REAR SIDE END PART POSITION/ WIDTH/FRONT SIDE END PART POSITION OF QUALITY MODIFIED REGION	CUT SECTION IMAGE (×200) THICKNESS: 300 μ m UPPER SIDE: REAR FACE (LASER LIGHT ENTRANCE SURFACE) LOWER SIDE: FRONT FACE (DEVICE SURFACE)	SKIRT WIDTH S

Fig. 24






Fig. 25



26/29






Fig. 26

Fig. 27




Fig. 28





Fig. 29



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record.

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:			
BLACK BORDERS			
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES			
☐ FADED TEXT OR DRAWING			
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING			
☐ SKEWED/SLANTED IMAGES			
COLOR OR BLACK AND WHITE PHOTOGRAPHS			
GRAY SCALE DOCUMENTS			
☐ LINES OR MARKS ON ORIGINAL DOCUMENT			
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY			
OTHER:			

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.